Appln. No. 10/777,278
Amdt. dated: October 4, 2004
Reply to Office Action of July 21, 2004
Attorney Docket No. 111334-135471

Amendments to the Specification:

Please replace the paragraph beginning at page 4, line 26, to page 5, line 7 by adding a sentence at the end as follows:

The above is an example only of but one type of use for the tool/pry bar. The tool is usable in many different ways and many different orientations. For example, it may be used to strip ceiling tiles from overhead, pry up heavy beams to permit a fork lift to slide under, or roll a large cylinder out of the way. The uses of such a pry bar are endless and the criteria is that the bar end, fulcrum and handle are arranged to enable the bar end tip to fit under the object to be pried, the fulcrum contact point positioned sufficiently close and in contact with a support, the bar end configured so as to enable the bar end tip to slide under the object, and with the handle sufficiently extended from the fulcrum to allow the user to apply a desired force to enable the user's leveraged force (arrow 24) to achieve raising of the object. Hereafter, such uses of such a pry bar is referred to as pry bar tasks.

BEST AVAILABLE COPY

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
	□ BLACK BORDERS
	☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
	☐ FADED TEXT OR DRAWING
	☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
	☐ SKEWED/SLANTED IMAGES
	☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
	☐ GRAY SCALE DOCUMENTS
	☐ LINES OR MARKS ON ORIGINAL DOCUMENT
	☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
	OTHER.

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.